

TECHNICAL SERVICES BULLETIN

Tire Label misprint

9/8/2025 Revision 2

Yokohama has delivered some tires that were labeled improperly. Some labels include a mismatch of the numerical "ply rating" and load range letter. The tire sidewall stamping on these tires is correct. The mismatch may cause confusion during tire selection or inventory management but does not affect tire performance.





In the photo above, the label on the left ("G") is correct. The label on the right ("H") is a misprint.

Tires affected:

Part Number	Production Range
	(DOT TIN Week)
120110827	2825 - 3425
120110901	2125 - 3525
120110902	2125 - 3525
120110904	2125 - 3525
120151727	2825 - 3525
120161703	2425 - 3325
120170901	2225 - 3425

The DOT TIN week is comprised of the last 4 digits of the DOT TIN.

Example:

DOT 1FABTYJAE0824

The TIN week is 0824

The tire was manufactured in the 8th week of 2024

Note that not all tires in these production ranges are affected. Some labels in these ranges are correct.

Original Issue: 9/8/2025

What Yokohama Will Do:

Yokohama will replace the misprinted labels with correct labels.

What Dealers Should Do:

Dealers are requested to inspect inventory and replace the misprinted labels with corrected labels when they are available.

What End-users Should Do:

Tires already in operation will no longer have labels attached. The tires will operate as intended. These tires are safe to use and perform as intended.

For More Information:

Please call the Yokohama Warranty Operations Center 1-800-423-4544 x4401

Original Issue: 9/8/2025